


急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図

調査年度	平成24年度
------	--------

急傾斜地の位置	箇所番号	II-1222	箇所名	尾上1	所在地	印旛郡酒々井町尾上向小神
---------	------	---------	-----	-----	-----	--------------



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度 平成24年度

急傾斜地の位置	箇所番号	II-1222		箇所名	尾上1	所在地	印旛郡酒々井町尾上向小神				
危害の恐れのある土地の座標						著しい危害の恐れのある土地の座標					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-31019.45	41109.82				R-1	-31022.52	41123.07			
Y-2	-31005.92	41112.14				R-2	-31008.75	41124.92			
Y-3	-31006.53	41114.91				R-3	-31009.33	41127.55			
Y-4	-31008.08	41121.90				R-4	-31023.25	41126.23			
Y-5	-31008.75	41124.92				R-5	-31022.52	41123.07			
Y-6	-31009.68	41129.14									
Y-7	-31010.91	41134.69									
Y-8	-31024.78	41132.81									
Y-9	-31023.40	41126.88									
Y-10	-31022.52	41123.07									
Y-11	-31021.71	41119.56									
Y-12	-31020.07	41112.48									
Y-13	-31019.45	41109.82									